Julie Independence Tomchak
Full Name of Party Filing Document
•
7805 U.S. Highway #98 North Lot 29
Mailing Address (Street or Post Office Box)
,
Lakeland, FL 33809
City, State and Zip Code
•
603-491-2415
Telephone

Letfreedomringnewengland@gmail.com

Email Address (if any

HEARING OCTOBER 23, 2019 AT 10 AM

Molayana (1975) 200 an 19 mara (1976)

IN THE UNITED STATES BANKRUPTCY COURT FOR THE <u>SOUTHERN</u> DISTRICT FOR THE STATE OF NEW YORK, IN AND FOR THE COUNTY OF **WESTCHESTER**

Plaintiff,
vs.

SEARS HOLDINGS CORPORATIONS, et al.,
Defendant (Debtors)

Julie Independence Tomchak

Case No. <u>18-23538 (RRD)</u> (Jointly Administered)

MOTION ADDENDUM FOR ORGINAL MOTION DOCUMENT # 4209 HEARING OCTOBER 23, 2019 AT 10 AM.

EXHIBITS ATTACHED TO COURT AS WELL AS OTHER PARTY, DUE TO TELEPHONIC HEARING

The X Plaintiff is filing a motion to explain case in better detail with exhibits to prove case.

- On 9/28/2017 I took my Ford F250 Super Duty pick up into sears for an oil change. After the oil change, I drove the truck up to Webster NH and parked the truck until 3/15/2018. Please note on (Exhibit 1), it lists that only 5 quarts of 5w20 conv Oil was placed in the truck.
- 2. On 3/15/2018 my brother begins to drive the truck pulling a 5th wheel camper from Webster NH to Idaho. According to my brother only 30 minutes from leaving the truck was acting funny and he was pulled into a snowbank. My brother said he checked the oil because the cap had blown off and there was no oil (Exhibit 4: picture of no oil cap). He said he added almost 2 gallons of oil that cost him between 40-50 dollars. He also had to pay Hayes to come help him pull the truck and camper out of the snow bank after he got

- oil in the truck. See bill for Hayes for 100.00 (Exhibit 2).
- 3. I get to Idaho in March 28, 2018 and express my concerns with Sears, who refer me to their 3rd party insurance adjuster Sedgwick. I set up a claim with a man named Samuel Saldivar. He said that I need to pay and have someone show the damage. So, I take the truck to John's Repair on 4/13/2018 and pay them to give me an estimate to repair the engine of \$6,896.39 (Exhibit 3b). They charge me \$157.39 (Exhibit 3a) for the estimate and drive the truck around but can't say for sure the extent of the damage. They do give me an invoice that states 6 Quarts Synthetic 5-20 should be added (Exhibit 3c).
- 4. I give the findings to Sedgwick, but instead of reaching Samuel his direct supervisor is covering for him that day and says that I can't prove they (Sears) damaged the truck, that I would have to have pay out the money to repair the damaged engine and pull it apart to prove damages. They would send someone out to take pictures of damages before they would be willing to pay out any money. He certainly didn't sound like a fair 3 party insurance representative. I personally feel they were trying to take advantage of me because I am a woman. I then call around to a different mechanic to get a second opinion. I reached out to Thompson Auto Repair. On 5/24/2018 I stopped and talked to Mr. Thompson. He did a quick research on the engine requirements and printed out that 6 Quarts were definitely required. (Exhibit 5b).
- 5. On June 20, 2018 and July 18, 2018 (Exhibits 6a and 6b respectively) I get notices from Sedgwick, expressing they want me to pay for all damages first before they would accept responsibility. I express to them that I have a second mechanic willing to look at the engine but has a long wait for an opening. I told Sedgwick that I was having an oil analysis done and requested if they had a preferred company they worked with or accepted. They said they didn't care what company that I used for the analysis. I asked Mr. Thompson to use a reputable company that he was familiar with using.
- 6. On Oct 3, 2018 Mr. Thompson was able to get the oil test kit done and set off, my bill was \$103.31 (Exhibit 7).
- 7. On Oct 12, 2018 the results were completed (Exhibit 8a, 8b, 8c and 8d). After talking to Mr. Thompson, he said that the high aluminum indicated to him that the pistons, camshafts and where it turns at the heads were damaged. I called Sedgwick with the results and they said well sorry to tell you this, but sears just filed for bankruptcy a week ago. You case is not going to be tossed into the bankruptcy courts we are no longer handling you case.
- 8. I then call a bankruptcy lawyer and he says, Sears can't toss an insurance claim into the

bankruptcy. That there are national insurance laws that require insurance claims to be handled in a time appropriate manner. So now I have been waiting over 2 years to get this claim resolved that should have been resoled by Sear's insurance company over a year ago. Sadly, once something is tossed in bankruptcy no one bothers to call you back and you get the run around calling in loops. This is certainly not ethical behavior on an issue that Sear's insurance should have covered, that Sears is making a layman go to court to try and get them to pay for something that has nothing to do with their bankruptcy but their liability insurance.

9. (All the above Exhibits are enclosed to court as well as other party.)

Date: October 17, 2019

Signature

Signature

OF SERVICE

Notary Public - State of Florida
Commission # GG 139585

My Comm. Expires Oct 21, 2021

I certify that on (date)

October 17, 2019

I served a copy to: (name all parties in the case other than yours)

Sunny Singh of WEIL, GOTSHAL & MANGES LLP	By United States mail
(Name)	By personal delivery By fax (number)
767 Fifth Avenue (Street or Post Office Address)	Exhibits Listed:
New York, NY 10153 (City, State, and Zip Code)	Exhibit I Sears recipt
Attorneys for Debtors	Exhibit 2 Tow Bill & oil cost Exhibit 3a 1st Medianic Bil
	3b Estimate of Repair 3c 6 Quarts of 011 Exhibit 4 Photo of Wound oil
(Name)	By United States mail By personal delivery By fax (number)
(Street or Post Office Address)	Exhibit Sa fluid Capacities 56 6 Quarts of 0112
(City, State, and Zip Code)	56 Quarts of oils
Julie Tomchak Typed/printed name	Signature Comchak
xhibit 6a, 6b, 6c letters	
on Sedgwick dated	DEE ANN VAUGHN
hibit 7 2nd Mechanic Oill	Notary Public – State of Florida Commission # GG 139585
hibit 8a, 8b, 8ea 8d Lubricant	Remet

Exhibited 2353835 SEALS AUTO CENTER

oc 5483 Fried 10/23/19 13:03:54 Main Document

Pg 4 of 19 6334 - Sears Operations LLC 1500 S WILLOW ST MANCHESTER, NH 03103 (603) 628-5295

FINAL INVOICE INVOICE DATE: 09/28/2017

EPA Number:

Facility Number:

			,,,,,		,				
NAME: TOMSHAK, JULIE	PROMISED:	09/28/2	2017 06:0	0 PM	INITIAL ES	TIMATE	REVISED ESTIMATE	PHONE AUTHORIZATION	REF. NUM.
ADD: PO BOX 129	YEAR/MAKE/MODEL				PARTS	\$21.84	\$21.84		IN6729827
LEADORE, ID 83464	1999 FORD TRUCK F	250 SUPER DU			LABOR	\$15.25	\$15.25	APPROVED BY:	CREATED BY:
PRI: (603) 494-3243, SEC:	LICENSE #	<u>C</u> (<u>OLOR</u>	<u>ODO. IN</u> 350123	OTHER	-\$13.00	-\$24.30		770115
TIRE INSTALLATION INSTRUCTIONS	- '				TAX	\$0.00	\$0.00	CONTACTED BY:	INVOICED BY:
	A'I'N'	<u>LC</u> IN	CATION	ODO. CUT	TOTAL	\$24.09	\$12.79		770115
RF RF	-				DATE/TIM	E OF	DATE/TIME REVISED	NUMBER CALLED:	LOCAL ·
	TIME IN 09/28/2017 04:13 PM		<u>ME OUT</u> V28/2017 04:15 F	PM	ESTIMA	NTE .			LOCAL PURCHASE PO NUMBER:
	TAG#				09/28/2017 0	4:13 PM	09/28/2017 04:15 PM	DATE / TIME CALLED:	729827
LA RA		WAITING							
AIR PRESSURE FRONT / REAR	WHL. TORQUE SPEC	IFICATION	See rev	verse for im	ı portant warrar	ntv terms	BY SIGNING BELOW I ACH	NOWLEDGE RECEIPT AND	O AGREE TO
58/80 - ALL O.E. APPLICATIONS	HND TOR/150-165 - A APPLICATIONS		and oth	her informat	ion.	.,	CHARGE THE INVOICE PF	RICE WITH AMOUNTS AS S ED HEREON, AND BE BOUN	SHOWN CHARGED ND BY THE TERMS
COMMENTS/REQUESTS OR ALTERNATE	CONTACTS:						WORK AUTHORIZED BY /	CREDIT APPROVED BY:	
							X		
QTY ITEM# DESCI	RIPTION OF MERCHANI	DISE P	RICE EACH	TOTAL	TECH	CSA	RETAIN FOI	R COMPARISON WITH MON	лні ү
	51,OIL FILTER s redeemed: 1970		\$3.49 \$1.97	\$3.49 \$1.97		770115 770115	STATEMENT	OR FOR RETURN OR EXC	HANGE
1 PS 19045062 5Qts 5	w20 Conv Oil		\$11.25	\$11.25		·770115	REWARDS	CARD #: XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	2735
	s redeemed: 3540 HANGE, SERVICE		\$3.54 \$15.25	\$3.54 \$15.25	659821	770115 770115	Parts Subtotal:		\$21.84
1 RD 57 syw pts	s redeemed: 4810		\$4.81	\$4.81	-	770115	Labor Subtotal: Reductions Subtota	d:	\$15.25 \$0.00
	0.1 QT 5W20CON s redeemed: 980		\$0.31 \$0.98	\$3.10 \$0.98		770115 770115	Subtotal: Tax:		\$12.79 \$0.00
1 AC 189022 Shop F	ee		\$4.00	\$4.00	252224	770115	Total:	U	ISD \$12.79
	RCAR,COURTESY CK RHOOD,COURTESY CK		\$0.00 \$0.00	\$0.00 \$0.00	659821 659821	770115 770115	RC: 7489-7040-323	9-2979-0619	
# 1 PS 02801315 SUGG	EST, TIRE(S)		\$0.00	\$0.00 -\$13.00		770115 770115	Credit Tendered:		\$12.79
	oupon 40228		-\$13.00	-\$13.00		770115	0455 7/55	MAG	STERCARD
# - This symbol indicates parts or labor ch	anged or are additional to	o the original es	stimate.				CARD TYPE : ACCT #:		********6447
•	SEARS VALUES	VOLID EEE	DDACKI				AUTH CODE:	TAI.	02808B \$12.79
	SEARS VALUES	TOUR FEE	DDACKI				MASTERCARD TO AID :	A0000	000041010
We hope we lived up to your ex	cpectations. Please	let us know	at WWW.SE	ARSAUTO	FEEDBACK.	СОМ	Application Preferre		MasterCard A-Signature
			1404841	DE ADOALIT	-OEEEDD & O	K COM			•
Esperamos haber sobrepasado s	sus expectativas. Ha	aganos sabe	er en vvvvv.	SEAHSAUT	OFEEDBACI	K.COW		R REDEMPTIONS THIS TRI REDEEMED WORTH: \$11.3	
							,		
						1	Cu	rrent Points Balance: 97	
							В	ase Points Earned: 88 onus Points Earned: 0	
								onus Points Earned: 0 s Expiring 09/30/2018 : 97	
							Pts exp da	ates vary.See SYWR.com/FA	IQ.
							,	/isit us at SYWR.com	
							SALES	SCHECK # 063340672024	

ITEM / WARRANTY INFORMATION / LABOR DETAILS / COMMENTS

6 Qts 5w20 Conventional Oil

Aftermarket TPMS Available. Verify TPMS.

ITEM COMMENTS:


02801315: Suggested tire(s). Recommendation based on conditions found during a visual inspection of the tires. See associate for details

ALL LUG NUTS ON CUSTOM AND ALLOY WHEELS MUST BE RE-TORQUED AFTER 25 MILES AND CHECKED PERIODICALLY.

189022 SHOP FEE: This charge represents costs and profits to the motor vehicle repair facility for miscellaneous shop supplies or waste disposal.

ALL NEW, NON-OEM PARTS UNLESS OTHERWISE SPECIFIED.







DATE 3.15. 2018

(603) 446-7755

-9	when Tomchale						
TERMS:	Due upon receipt. Delinquent accounts are so to a late charge of 1½% per month (18% per annum). PLEASE DETACH AND RETURN WITH YOUR		-	* *_			
DATE	INVOICE NUMBER / DESCRIPTION	CHAR	GES.	CREI	शांद्ध	BALAN	CE
	BALANCE FORWA	ARD (*
2a	ugo-panel "	100	00				
	las Trucla						
, -						_	
	#40 00 c//	mul	(مند)	Hici	;		
	put in						
	put in 157.39	st o) cho	P Maria			
	to engine	Z	ر ربلو		<u>e —</u>		
	io soluțioi .						
							
					,		
						<i>-</i>	
HAYES	CAR AND TRUCK REPAIR, LLC	TH	AN	к үо	<u> </u>	PAY LAST AMO IN THIS COLUM	UNT MN

Exhibit 5 n

Doc 5483

Filed 10/23/19 Entered 10/23/19 13:03:54 Main Document

John's Repair 6 of 19

Blackfoot, ID. 83221

1030 W Bridge St / P.O. BOX 1411

Phone: 208-681-5646 Fax:

INVOICE

8715

Org. Est. # 005119

INVOICE

Date: 04/13/2018

TOMCHAK, JULIE

PO BOX 129

Leadore, ID 83464

1999 Ford - Pickup F250 Super Duty - 5.4L, V8 (330CI) VIN(L)

Odometer In: 355917

VIN #: 1FTNF21L0 XEC45709

Part Description / Number	Qty	Sale	Ext Labor Description	Hours	Ext
Shop Supplies			8.00 TEST DRIVE, CHECK OUT ENGINE, CREATE ESTIMATE	2.00	140.00

Lic#:

TEST DRIVE, CHECK OUT ENGINE, CREATE ESTIMATE

140.00 Org. Estimate 148.48 Revisions 0.00 **Current Estimate** 148.48 Labor: Parts: 8.00 148.00 SubTotal: 0.48 Tax:

[Payments -] Vehicle Received: 4/13/2018

Customer Number: 891

148.48

\$148.48

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature Date Total:

Bal Due:

Ex 128-38-34-341



John's Repair 1030 W Bridge St./ Eptered 10/23/19 13:03:54

Blackfoot, ID. 83221 Phone: 208-681-5646 Fax:

Main Document 8714

N	V	\mathbf{O}	l	С	E

Date: 04/13/2018

Org. Est. # 005118

TOMCHAK, JULIE PO BOX 129

Leadore, ID 83464

1999 Ford - Pickup F250 Super Duty - 5.4L, V8 (330CI) VIN(L)

Lic#:

Odometer In: 355917

VIN #: 1FTNF21L0 XEC45709

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext

Org. Estimate	6,896.39	Revisions	0.00	Current Estimate	6,896.39	Labor:	2,125.00
			٠			Parts:	4,501.31
						SubTotal:	6,626.31
						Tax:	270.08
						Total:	6,896.39
[Payments -]						Bal Due:	\$6,896.39

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

original obot of repair.	
Signature	Date

EX 18,723538-shl Boc 5483

Filed 10/23/19 Entered 10/23/19 13:03:54 Main Document John's Repaig 8 of 19

1030 W Bridge St / P.O. BOX 1411 Blackfoot, ID. 83221

Phone: 208-681-5646 Fax:

INVOICE

8714

Org. Est. # 005118

INVOICE

Date: 04/13/2018


TOMCHAK, JULIE **PO BOX 129**


Leadore, ID 83464

1999 Ford - Pickup F250 Super Duty - 5.4L, V8 (330CI) VIN(L) Lic#: Odometer In: 355917

				VIN #: 1FTNF21L0 XEC45709		
Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
LONG BLOCK ENGINE	1.00	3,875.00	3,875.00	R+R LONG BLOCK ENGINE, SWAP PARTS FROM OLD ENGINE TO NEW, INSTALL	25.00	2,125.00
6 QUARTS SYNTHETIC 5-20 SERVICE	1.00	73.99	73.99	NEW PARTS AS NECESSARY R+R LONG BLOCK ENGINE, SWAP PARTS F TO NEW, INSTALL NEW PARTS AS NECESSA		NGINE
ENGINE COOLANT STOCK	5.00	11.49	57.45			
AIR FILTER AVA	1.00	34.47	34.47			
FUEL FILTER AVA	1.00	21.79	21.79			
SPARK PLUGS AVA	8.00	5.49	43.92			
SPARK PLUG COIL BOOT SET AVA	1.00	61.94	61.94			
UPPER RADIATOR HOSE AVA	1.00	26.44	26.44			
LOWER RADIATOR HOSE AVA	1.00	118.78	118.78			
PCV VALVE AVA	1.00	7.46	7.46			
CLEANER STOCK	4.00	6.49	25.96			
THERMOSTAT AND GASKET AVA	1.00	23.68	23.68			
ENGINE PAINT AVA	3.00	14.71	44.13			
SERPENTINE BELT AVA	1.00	60.36	60.36			
HOSE CLAMPS STOCK	6.00	2.99	17.94			
Shop Supplies			8.00			

Estimate Cost + 157.39







18-23538-shl; Doc,5483 Filed 10733/19 ZEntered 20/23/19 13:03:54 Main Document FX hibit 5a

1999 Ford Pickup 5.4L Eng VIN L F250 Super Duty

Print Date: 5/24/2018

FLUID CAPACITIES

Fluid Type	Application		Standard	Metric	Fluid Spec	Note	S/H
Air Cond Compressor Oil			9.00 OZS.	0.3 L	PAG 46		s
Air Cond Refrigerant			2.38 LBS.	1.1 KG	R-134a		s
Automatic Transmission Fluid	F250 Super Duty,F350 Super Duty,Trans Mfr CD 4R100	w/Large Cooler	17.70 QTS.	16.8 L	Automatic Transmission Fluid MERCON		S
Automatic Transmission Fluid	F250 Super Duty,F350 Super Duty,Trans Mfr CD 4R100	w/Small cooler	17.10 QTS.	16.2 L	Automatic Transmission Fluid MERCON		S
Brake Fluid			N/A	N/A	MOTORCRAFT High Performance DOT 3 Motor Vehicle Brake Fluid	Fill to line on reservoir.	S
Differential Gear Oil	4WD	Front	3.70 PTS.	1.8 L	SAE 75W-90 Gear Oil		s
Differential Gear Oil	F250 Super Duty,F350 Super Duty	Front,w/(Dana 50)	3.80 PTS.	1.8 L	SAE 75W-90 Front Axle Gear Oil		s
Differential Gear Oil	F250 Super Duty,F350 Super Duty	Rear,w/10.50" Axle	6.90 PTS.	3.3 L	SAE 75W-140 Synthetic Rear Axle Gear Oil	Your vehicle's rear axle(s) may be filled with a synthetic lubricant that may required a lubricant change. Axle	S

18-23538 Shi Doc 5483 Filed 10/23/19 Entered 10/23/19 13:03:54 Main Document

			V- V OP	1 11 01×19	0-06			
Exh	iibit s	Duty,5.4L Eng				Extended Life Engine Coolant	Premium Cooling System Fluid. If it is (orange color) use: FORD Extended Life Engine Coolant.	
	Engine Coolant	F250 Super Duty,F350 Super Duty,5.4L Eng	w/o Air Cond	17.90 QTS.	16.9 L	FORD Premium Cooling System Fluid or FORD Extended Life Engine Coolant	If the vehicle's coolant is (green color) use: FORD Premium Cooling System Fluid. If it is (orange color) use: FORD Extended Life Engine Coolant.	S
	Engine Oil	Gas	w/Filter	6.00 QTS.	5.7 L	SAE 5W-20 Premium Synthetic Blend Motor Oil	Refer to Engine Oil recommended applications for SAE 5W- 20 and 5W-30 motor oils TSB No. 02-1-9.	S
	Fuel Tank	4WD,Pickup	Regular cab (Short wheel base)	24.50 GALS.	92.7 L			s
	Fuel Tank	F250 Super Duty,F350 Super Duty	Long Box Wide Frame	38.00 GALS.	143.8 L			s
	Fuel Tank	F250 Super Duty,F350 Super Duty	Shortbed Models	29.00 GALS.	109.8 L			S
	Fuel Tank		Long Wheelbase	30.00 GALS.	113.6 L			S
	Fuel Tank	RWD	SuperCab,Regular cab (Short wheel base)	25.00 GALS.	94.6 L		,	S
		F250 Super Duty,F350		3.40 QTS.	3.2 L	Synthetic Automatic		S

Sedgwick Claims Management Services, Inc. P O Box 14448 Lexington, KY 40512-4448



Phone: (866)352-1521 Fax: (866)876-7050

June 20, 2018

Julie Tomchak Po Box 129 Leadore ID 83464

RE:

Claimant Name:

Julie Tomchak

File Number:

L1803285026-0001

Date of Incident::

03/28/2018

Store Number:

MANCHESTER, NH

Dear Julie Tomchak:

This letter is to advise you we have recently received notice of this matter.

Please be advised that Sedgwick is the Third Party Claims Administrator for Sears, Roebuck and Co., and I am the examiner assigned to your file. On behalf of Sears, I would like to apologize for any inconvenience this incident may have caused.

If we have not yet had the opportunity to speak, please contact me at (847)645-0675 so that we can discuss the details of your claim.

Sincerely,

Samuel Saldivar Claims Representative (847)645-0675 Sedgwick Claims Management Services, Inc.







Sedgwick Claims Management Services, Inc. P O Box 14448 Lexington, KY 40512-4448



Phone: (866)352-1521 Fax: (866)876-7050

July 18, 2018

Julie Tomchak Po Box 129 Leadore, ID 83464

Re:

Claim Number:

L1803285026-0001

Date of Incident:

03/28/2018

Dear Madam:

Sedgwick Claims Management Services, as a Third Party Administrator, manages claims for Sears, Roebuck and Co. on behalf of ACE American Insurance Company. Per our discussion the inspectors report shows no signs that Sears caused any damage to your vehicle. To give your claim further consideration a tear down is recommended. If the diagnosis does not reveal any liability on the part of my client, then no payments will be issued, including the cost for teardown. If the diagnosis reveals Sears is liable you will be reimbursed. Please schedule tear down with shop of your choice and please give me 24/48 hour notification to notify my inspector.

If I do not hear from you within fourteen (14) days from the date of this letter, I will assume you are not pursuing a claim and we will close our file.

If this claim is not resolved within three year of the date of this incident, only your filing of a legal action will preserve your right to pursue this matter.

Sincerely,

Samuel Saldivar Claims Representative Sedgwick Claims Management Services, Inc Samuel.Saldivar@sedgwickcms.com (847)645-0675

CC

!C24662209.339-1845!





Sedgwick Claims Management Services, Inc. P O Box 14448 Lexington, KY 40512-4448



Phone: (866)352-1521 Fax: (866)876-7050

January 08, 2019

Julie Tomchak Po Box 129 Leadore ID 83464

RE:

Claimant Name:

File Number:

Julie Tomchak L1803285026-0001

Date of Incident:

03/28/2018

Store Number:

06334 STORE IN LIQUIDATION

Dear Ms. Julie Tomchak:

If you are not already aware, be advised Sedgwick Claims Management Services, Inc. is the Third Party Claims Administrator for Sears, Roebuck and Co.

Sears Holdings filed Chapter 11 bankruptcy on October 15th 2018. Sedgwick continues to administer claims for Sears Holdings but we are unable to make payments on any claims that occurred on or before October 14, 2018 due to Sears Holdings' Chapter 11 bankruptcy. Claims made during that timeframe will be addressed by the bankruptcy court.

If you have a pending claim with us, you'll need to file a proof of the claim prior to the deadline established by the bankruptcy court.

You can obtain information about the bankruptcy and the process for filing a proof of the claim online through the Prime Clerk web site at https://restructuring.primeclerk.com/sears/EPOC-Index or you can contact Sears via U.S. Mail to:

Sears Holdings Corporation Claims Processing Center c/o Prime Clerk LLC 850 3rd Avenue, Suite 412 Brooklyn, NY 11232

The proofs of claim will be examined and evaluated and any payments will be subject to rulings by the bankruptcy court. Sedgwick will not be able to assist you in that process.

You can find further information at https://restructuring.primeclerk.com/sears/

Sedgwick manages claims on behalf of Sears Holdings Corporation.

Sincerely,

Bonita Taskov





b 45 5w-30 MTE 612 71 00 34 EAST 100 NORTH • BLACKFOOT, IDAHO 83221 1 61372 at 17th 400 PHONE: 785-4191 Year Make Date 1999 Ford Oct 3	R ORDER
BILL THOMPSON — Owner/Operator Bill THOMPSON — Owner/Operator AW FW HEPAIR Bill THOMPSON — Owner/Operator Bill TH	2018
1 61372 at filter 400 PHONE: 785-4191 Year Make Date 1999 Ford Oct 3	itten by
1 61372 at filter 4 00 PHONE: 785-4191 1999 Ford Oct 3	itten by
	itten by
1 65764 grund place 444 NAME Julie Tomchak F250 PE Boil	
1 Bit test Kit 35 00 NAME In Sec 10 MCNAK F250 PX Birth. License. Motor	r Number
ADDRESS 429 5297 5.41	SOHC
ADDRESS — 429 5297 5.42 When 705 971-1770 Purchase Order Speed	dometer
CITY Priorie When Ready Z08-921-8779 Waw Armpshive 35600	59
Order No. INSTRUCTIONS	AMOUNT
The bar to chinge and 4 filter 4 sind	3500
M Simple of for analysis	20
TOTAL	
SUBLET AUTHORIZATION	
Est. Cost of Repairs \$SUBLET	
I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate	
the above vehicle for the purposes of testing, inspection or delivery at my risk. An express mechanic's lein is acknowledged on the above vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, wind damage, accident or any other cause beyond your control.	200
ALL ALUMINUM WHEELS MUST BE RETORQUED.	35
Signed (Customer) TOTAL ADDITIONAL REPAIR AUTHORIZATION PARTS	111/11/
ADDITIONAL REPAIR AUTHORIZATION Name of Additional	64, 44
person Cost Authorized \$ TAY	200
Date	3-87
TOTAL A.M. PAY THIS AMOUNT 47/	03, 31

EX 18 93538 by Doc 5483 Filed 10/23/19 Entered 10/23/19 13:03:54 Lubricant Analyzers

North America: +1-877-458-3315

Main Document CRITICAL

Overall report severity based on comments.

Additional Testing

Account Information	Component Information	Sample Information
Account Number: OILANA-7502-2837 Company Name: THOMPSON AUTO REPAIR Contact: BILL THOMPSON Address: 34 EAST 100 NORTH BLACKFOOT, ID 83221 US Phone Number: 208-785-4191	Component ID: JULIE E Secondary ID: 1999 FORD F250 PK 5.4L 50HC Component Type: UNLEADED GASOLINE ENGINE Manufacturer: FORD Model: 5.4 L Application: AUTOMOTIVE Sump Capacity:	Tracking Number: 18129J02970 Lab Number: I-117672 Lab Location: Indianapolis Data Analyst: EAD Sampled: 03-Oct-2018 Received: 10-Oct-2018 Completed: 12-Oct-2018
Filter Information	Miscellaneous Information	Product Information
Filter Type: FULLFLOW Micron Rating: 0		Product Manufacturer: Information Requested Product Name: Information Requested Viscosity Grade: SAE 5W20

Comments ||Suggest monitoring the gauges, vital signs, fault codes and fluid level close LEVEL; ALUMINUM in UNLEADED GASOLINE ENGINES include intake manifold, cylinder heads, pistons and some block assemblies. Base Number is MODERATELY LOW. As Base Number depletes, the ability to neutralize acids is diminished. Sodium

is at a MODERATE LEVEL; Sodium sources: coolant (antifreeze), lube additive or supplement, and/or environmental contaminant; Water is at a MINOR LEVEL. Water may be present due to COLD UNIT sampling; Flagged data has been rechecked

land confirmed.

				Wea	ar Met	als (p	pm)					tamir als (p		М	ulti-Sc	ource	Metal	s (ppn	n)	A	dditive	Meta	ls (ppr	m)
Sample #	Iron	Chromium	Nickel	Aluminum	Copper	Lead	Tin	Cadmium	Silver	Vanadium	Silicon	Sodium	Potassium	Titanium	Molybdenum	Antimony	Manganese	Lithium	Boron	Magnesium	Calcium	Barium	Phosphorus	Zinc
1	33	0	0	51	8	3	0	0	0	0	16	123	13	0	18	0	0	0	81	17	2682	0	1071	1213

		Sample	e Infor	mation			F-173		Contaminants	- VOB-1 1145		F	luid Pr	opertie	S	
ple #	e Sampled	e Received	Lube Time	Unit Time	e Change	Lube Added	er Change	Fuel Dilution	Soot	Water	Viscosity 40°C	Viscosity 100 °C	Acid	Base No.	Oxidation	olysda Nitration
Sam	Date	Date	mi	mi	Lube	gal	Filte	% Vol	% Vol	% Vol	cSt	cSt	mg KOH/g	ISCORDED DE LA CONTRACTION DEL CONTRACTION DE LA	abs/cm	mm
1	03-Oct-2018	10-Oct-2018	5886	356009	Yes	0	Yes	<1 - Estimate	0.1 - E2412	0.1 - Hotplate		9.8		2.69	15	11

			A STAR	Particle	Count	(particl	es/mL)			
Sample #	ISO Code Based On 4/6/14	> 4 µm	> 6 µm	> 10 µm	> 14 µm	> 21 µm	> 38 µm	> 70 µm	> 100 µm	Test Method
1	//									

Comments are advisory only and are based on the assumption that the sample and data submitted are valid. Missing fluid or component information limits the evaluation. No warranty is expressed or implied. Measurement uncertainty available upon request.

Historical Comments

Instructions


Reading a Sample Report

These instructions will teach you about each section of the sample reports in HORIZON®.

- Sample Summary
- **Test Results**
- Graphs

Sample Summary

Open a sample report in HORIZON® using one of the methods in the "Find a Sample" instructions. The top of the report has all of the information you need to take action on the results.



Severity Scale

A color coded scale ranging in severity 0-4, the severity of this report is displayed in a larger box with a white number on a colored field. The overall report severity is based on comments, not individual test results.

Component Information

This area contains information about the account, component, sample, filter, product (fluid) and miscellaneous information. Some examples of miscellaneous information include the time the sample was taken or the initials of the person who took the sample.

The Comment section includes the analysis of the test results, including maintenance recommendations and feedback from our Data Analysis Team. These comments determine the overall severity of the report.



Pq 18 of 19

Test Results

The actual test results are included in the sample report. Results from past samples are displayed above the current results

		Wear Metals (ppm)									Contar	ninant M	letals (p	ррт)	Mult	Additive Metals (ppm)								
Sample #	Iron	Chromium	Nicke	Aluminum	Copper	Lead	Tinc	admiu	Silver	Vanadiu	m Silicon	Sodium	Potass	ium Titanium	Molybdenu	m Antimony	Manganes	Lithium	Boron	Magnesium	Calcium	Barium	Phospho	rous Zine
1	0	0	0	0 .	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	2	60	0	303	367
2	0	0	0	0	0	0	0	0	0	0	0	0	4	0	0	0	0	0	1	3	68	0	304	381
	100				15.33		200				题 接受							0.83	Et.	J D			是國際的	
	Sample Information											5.50	1	Contarr	Contaminants					Fluid Properties				
Sample #	Dat	te Sample	Date	e Received	Lube T		Unit '	Time a L	ube Cha	inge Lut	be Added	Filter C		Fuel Dilution	7	Viscosity .	40°C Visco	sity 100		oid Number mg KXXK'g	Base Nu mg KO		xidation abs'on	
1	13	3-Jan-2015	18-	Jan-2015					No	_		14	0			65.7	27570 257	3807335450	T	0.45	120-20-20-20-20-20-20-20-20-20-20-20-20-2		4	5
2	12	2-Mar-2015	16-	Mar-2015					Unk			Ur	nk			65.8				0.45			2	5

		25/41/16		0.00	Additional Testing							
Sample #	ISO Code	> 4 µm	> 6 µm	> 10 µ 300	SERVICE STREET	orean transfer	and the same	6 0 µт	> 100 µm	Test Method	Photo Micrograph	Water by Karl Fischer - D1744
1	** 17/15/11	990	211	52	17	and the second		0	0	Laser	CMPLT	103
2	17/15/12	992	227	51	22	9	1	0	0	Laser	CMPLT	219

Flagged data does not indicate an immediate need for maintenance action. Continue to observe the trend and monitor equipment and fluid conditions. Particle Count is at a MODERATE LEVEL. Please provide COMPONENT MODEL number to compare data to the correct standards for this component. Please provide FILTER MICRON RATING for proper particle count evaluation.


- The elemental analysis data will detect wear particles, contaminants, multisource metals and additive metals.
- 6 Other tests will be performed based on the fluid type and test package ordered.
- 6 Test results will have a colored background that coordinates with the severity of the scale at the top.
- Test fields with blue font contain a hyperlink to a description and additional information about the test, including possible sources.
- Historical Comments from previous sample reports are included along with the severity of the overall report.

Messages about the sample will be posted below the comments with a date stamp and the user who posted it.



Main Document

Graphs



All test results are displayed in Graphs to identify trends easily over multiple samples.

For additional questions about the HORIZON application, please contact us at custserv@eoilreports.com.

